

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

December 12, 2006

Mr. Mike Dalley Staker & Parson Companies 1730 North Beck Street Salt Lake City, Utah 84127-0598

Re: <u>Five-Year Review of Reclamation Surety Estimate, Staker & Parson</u>
Companies, Keigley Quarry, M0490001, Task ID # 1336, Utah County, Utah

Dear Mr. Dalley:

The Division has now been waiting for several months for your updated mine plan and maps for the Keigley Quarry. This was originally requested in August of 2003. The following is from the Division's August 19, 2003 letter:

The reclamation surety for Staker & Parson Companies' Keigley Quarry is due for review as of 2003. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Page 2 Mike Dalley M0490001 December 12, 2006

The Division been more than patient waiting for this to be submitted so that we can complete the update of the reclamation surety for this site. Please provide the requested update of the plan and maps by January 12, 2007. Failure to do so may result in the Division taking enforcement action. If you have any questions concerning this letter, please contact myself at (801) 538-5258 or Lynn Kunzler at 538-5310.

Sincerely,

Susan M. White Mining Coordinator

Minerals Regulatory Program

Suran M. White

pb
P:\GROUPS\MINERALS\WP\M049-Utah\M0490001-KeigleyQuarry\Final\5yrrev-12112006.doc